राजेश अरोरा, आई आर डल ई. मुख्य रेलपथ इंजीनियर



महाप्रबंधक कार्यालय इंजीनियरिंग विभाग, जबलपुर

General Manager's Office Engg. Department, Jabalpur

Date: 14.11.2019

Rajesh Arora, I.R.S.E.

Chief Track Engineer

West Central Railway

No. W-HQ/W-4/Track-II/Policy/Circulars/5

CTE PROCEDURE ORDER NO. 09/2019-20

Sr. DEN/Co. West Central Railways JBP / BPL / KOTA

Sub: Improvement to yard maintenance.

There have been several improvements to track structure in recent past. While this has enhanced the safety on P.Way account, our station yards still remain a cause of concern. Maximum derailments/unusuals on P.Way account are within the station yard. This calls for an increased inspections and maintenance input in the yards.

* * * * *

During various field inspections also, it has been observed that the conditions of yards as well as their maintenance is not up to the mark. Therefore, as a system improvement it has been decided that:

- (i) All Turnouts on Passenger lines: Henceforth, only detailed inspections to be done as per IRPWM Annexure-2/6. No intermediate inspection should be done at any level.
- (ii) All Turnouts: Separate register should be made for record keeping of critical parameters as mentioned in format below:-

Name of Station:		Point No.:		
(a)	Switch & Lead area (At every 3 m)			
(4-7	Station	Gauge	Cross level	
(b)	In crossing area (At every 1 m)	sing area (At every 1 m)		
(4)	Station	Gauge	Cross level	
(c)	Condition of Liner Seating			
(d)	Condition of Fittings			
(e)	Check-rail Clearance			

This register should be updated regularly and should be **carried by SSE/P-Way during inspection of higher officials.** It should be ensured by respective Sr.DENs/DENs/ADENs that the above register is updated on a regular basis.

Chief Track Engineer